



1

Cleaning/inspection



2

Measuring
gudgeon
pin hole



3

Before chroming



4

After chroming and grinding



5

Defric
coating



6

Final inspection
including coating measurement

RECONDITIONING PROCEDURE A/E PISTON CROWNS